



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

June 8, 2007

Supervisor DRH

Mine Name: Hi-Cal 1

Operator Name:
Robert Steele

Permit number: M230071

Inspection Date: May 24, 2007

Time: 3:30PM-3:45PM

Inspector(s): Tom Munson

Other Participants: none

Mine Status: Active

Weather: Sunny

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

To determine if reclamation had been completed.

Directions to Site:

The site is about 15 miles west of Nephi, Utah.

Inspection Summary:

The site had been fully regarded and there was some evidence of seeding. It is important to note that this is the wrong time of year to seed and it will be the reason to keep extra bond money for reseeding if it needs to be redone.

Conclusions and Recommendations:

The Division recommends that the operator keeps his seed tags and present them to the Division as there was an approved seedmix for the site. Also Mr. Steele should provide evidence that the site was seeded.

Inspector's Signature Thomas Munson

Date: 04/06/2006

tm:pb

cc: Robert Steele, Operator
Jerry Mansfield, BLM, Fillmore

Attachment: Photos

O:\M023-Juab\M0230071-HiCal\inspections\insp-05242007.doc





M 023/071
5/29/07



m/023/071
5/24/07



M/023/071
5/24/07



M/023/071
5/24/07



m/023/071
5/24/07



m/023/071
5/24/07



M/023/071

5/24/07